

## HG toilet renovation kit

- removes even the most stubborn stainsgives your toilet pan a new lease of life
- extremely powerful

The glaze on a toilet pan becomes more porous as it gets older. Deposits such as limescale or uric scale stick to it more easily and mix with other dirt. These generally persistent deposits are not only found in the visible parts of the toilet, (such as the neck, for example), but also hidden under the rim.

The deposits under the rim of the toilet pan prevent the toilet from ever being truly hygienically clean and leaves a persistently musty smell in the toilet. Deposits under the rim reduce the flushing action of the toilet.

The *HG toilet renovation kit* can be used to remove these deposits effectively. The content of this *HG toilet renovation kit* consists of the following products:

• 1 bottle of *HG toilet renovation* cleaner, a super powerful cleaner, developed especially to remove even the most persistent deposits from the toilet pan



- 1 absolutely non-scratch, but extremely effective, *HG scrubbing pad* to remove even the most persistent deposits
- 1 convenient HG scrubber, for easy scrubbing of the inside of the pan and for scrubbing under the rim and in the neck
- 2 plastic gloves



The specially developed formula of *HG toilet renovation cleaner* adheres to the surface of the pan and, in combination with the handy scrubber and the absolutely non-scratch, but extremely effective, scrubbing pad, it ensures removal of the most persistent deposits. After use, the toilet pan is truly hygienically clean and fresh smelling again, giving it a new lease of life. **Transport and store the box upright.** This product is not suitable for septic tanks

Medical personnel can request the data sheet via +31 36 54 94 777

The consumer's information sheet can be obtained via www.HG.eu



## toilet renovation kit



## HG toilet renovation kit

- removes even the most stubborn stains
- gives your toilet pan a new lease of life
- extremely powerful

The glaze on a toilet pan becomes more porous as it gets older. Deposits such as limescale or uric scale stick to it more easily and mix with other dirt. These generally persistent deposits are not only found in the visible parts of the toilet, (such as the neck, for example), but also hidden under the rim.

The deposits under the rim of the toilet pan prevent the toilet from ever being truly hygienically clean and leaves a persistently musty smell in the toilet. Deposits under the rim reduce the flushing action of the toilet.



0631800100106 2108 Products and tips? See: **HG. EU** Consumer Services?



contains a.o.:

non-ionic surfactants

amphoteric surfactants

< 5%

< 5%

DANGER H314- Causes severe skin burns and eye damage. H412- Harmful to aquatic life with long lasting effects. P101- If medical advice is needed, have product container or label at hand. P102- Keep out of reach of children. P280- Wear protective gloves and eye protection. P301+P330+ P331- IF SWALLOWED: rinse mouth. Do NOT induce vomiting. P303+P361+ P353- IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].P305+P351+P338- IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P501- Dispose of contents and container in accordance with all local, regional, national and international regulations.Contains: Glycolic acid, EINECS: 201-180-5.

Made in The Netherlands by HG International b.v., P.J. Oudweg 41, 1314 CJ Almere, Tel.: 036 54 94 700

## HG Does what it promises.

UK importer: HG Hagesan (UK) Ltd, Weston Business Centre, Parsonage Road, Takeley, Essex, CM22 6PU. Tel.: +44 (0) 1206 822 744

